



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 /

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 041733323
Customer ID: TTIE54
Customer PO: 023938
Project ID:

Attention: Jim Guilardi TTI Environmental Inc. 1253 North Church Street Moorestown, NJ 08057	Phone: (856) 840-8800 Fax: (856) 840-8815 Received Date: 11/17/2017 9:20 AM Analysis Date: 11/17/2017 Collected Date: 11/16/2017
Project: 17-1224 / Pinelands Regional BOE / Pinelands High School Annex	

Test Report: Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Appendix A to Subpart E

Sample	Location	Volume (Liters)	Area Analyzed (mm ²)	Non Asb	Asbestos Type(s)	#Structures		Analytical Sensitivity (S/cc)	Asbestos Concentration	
						≥0.5μ < 5μ	≥5μ		(S/mm ²)	(S/cc)
C-01	Inside Annex - Rainbow Room	1300.00	0.0645	0	None Detected	0	0	0.0046	<16.00	<0.0046
041733323-0001										
C-02	Inside Annex - Rainbow Room	1270.00	0.0645	0	None Detected	0	0	0.0047	<16.00	<0.0047
041733323-0002										
C-03	Inside Annex - Tech Lab 02	1260.00	0.0645	0	None Detected	0	0	0.0047	<16.00	<0.0047
041733323-0003										
C-04	Inside Annex - Tech Lab 02	1220.00	0.0645	0	None Detected	0	0	0.0049	<16.00	<0.0049
041733323-0004										
C-05	Inside Annex - Tech Lab 03	1230.00	0.0645	0	None Detected	0	0	0.0049	<16.00	<0.0049
041733323-0005										

Analyst(s)

Sandy Burany, Ph.D (5)

Benjamin Ellis, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMSL is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. Samples received in good condition unless otherwise noted. The test results meet the requirements of NELAC unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from: 11/17/2017 3:34:38 PM