



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077
Phone/Fax: (800) 220-3675 / (856) 786-5974
<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order ID: 041825222
Customer ID: TTIE54
Customer PO: 025980
Project ID:

Attn: Jim Guilardi
TTI Environmental Inc.
1253 North Church Street
Moorestown, NJ 08057

Phone: (856) 840-8800
Fax: (856) 840-8815
Collected: 8/20/2018
Received: 8/20/2018
Analyzed: 8/21/2018

Proj: 17-1224 / Pinelands Regional School District / Pinelands Regional Junior High

Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

Client Sample ID: 0820-01-01

Lab Sample ID: 041825222-0001

Sample Description: D Hallway 2nd Floor Girls' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	8/21/2018	White	0%	100%	None Detected	

Client Sample ID: 0820-01-02

Lab Sample ID: 041825222-0002

Sample Description: D Hallway 2nd Floor Girls' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
TEM Grav. Reduction	8/21/2018	White	0.0%	98.6%	1.4% Anthophyllite	

Client Sample ID: 0820-02-03

Lab Sample ID: 041825222-0003

Sample Description: D Hallway 2nd Floor Boys' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	8/21/2018	White	0%	100%	None Detected	

Client Sample ID: 0820-02-04

Lab Sample ID: 041825222-0004

Sample Description: D Hallway 2nd Floor Boys' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
TEM Grav. Reduction	8/21/2018	White	0.0%	97.8%	2.2% Anthophyllite	

Client Sample ID: 0820-03-05

Lab Sample ID: 041825222-0005

Sample Description: C Hallway 2nd Floor Girls' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	8/21/2018	White	0%	100%	None Detected	

Client Sample ID: 0820-03-06

Lab Sample ID: 041825222-0006

Sample Description: C Hallway 2nd Floor Girls' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
TEM Grav. Reduction	8/21/2018	White	0.0%	100%	None Detected	

Client Sample ID: 0820-04-07

Lab Sample ID: 041825222-0007

Sample Description: C Hallway 2nd Floor Boys' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	8/21/2018	White	0%	100%	None Detected	



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-5974
<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order ID: 041825222
 Customer ID: TTIE54
 Customer PO: 025980
 Project ID:

Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

Client Sample ID: 0820-04-08 **Lab Sample ID:** 041825222-0008

Sample Description: C Hallway 2nd Floor Boys' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
TEM Grav. Reduction	8/21/2018	White	0.0%	100%	None Detected	

Client Sample ID: 0820-05-09 **Lab Sample ID:** 041825222-0009

Sample Description: C Hallway 1st Floor Girls' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	8/21/2018	White	0%	100%	None Detected	

Client Sample ID: 0820-05-10 **Lab Sample ID:** 041825222-0010

Sample Description: C Hallway 1st Floor Girls' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
TEM Grav. Reduction	8/21/2018	White	0.0%	100%	None Detected	

Client Sample ID: 0820-06-11 **Lab Sample ID:** 041825222-0011

Sample Description: C Hallway 1st Floor Boys' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	8/21/2018	White	0%	100%	None Detected	

Client Sample ID: 0820-06-12 **Lab Sample ID:** 041825222-0012

Sample Description: C Hallway 1st Floor Boys' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
TEM Grav. Reduction	8/21/2018	White	0.0%	100%	None Detected	

Client Sample ID: 0820-07-13 **Lab Sample ID:** 041825222-0013

Sample Description: B Hallway 1st Floor Girls' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	8/21/2018	White	0%	100%	None Detected	

Client Sample ID: 0820-07-14 **Lab Sample ID:** 041825222-0014

Sample Description: B Hallway 1st Floor Girls' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
TEM Grav. Reduction	8/21/2018	White	0.0%	98.3%	1.7% Anthophyllite	

Client Sample ID: 0820-08-15 **Lab Sample ID:** 041825222-0015

Sample Description: B Hallway 1st Floor Boys' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	8/21/2018	White	0%	100%	None Detected	



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077
Phone/Fax: (800) 220-3675 / (856) 786-5974
<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order ID: 041825222
Customer ID: TTIE54
Customer PO: 025980
Project ID:

Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

Client Sample ID: 0820-08-16

Lab Sample ID: 041825222-0016

Sample Description: B Hallway 1st Floor Boys' RR/Caulking Material (Base of Toilet)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
TEM Grav. Reduction	8/21/2018	Tan/White	0.0%	98.7%	1.3% Anthophyllite	

Analyst(s):

Frank Dicrescenzo PLM (8)
Garret Vliet TEM Grav. Reduction (8)

Reviewed and approved by:

Benjamin Ellis, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM alone is not consistently reliable in detecting asbestos in floor coverings and similar NOBs.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036

Initial report from: 08/21/2018 13:35:03